

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS  
OKLA.  
68-5454,  
1A-

Dwight Mission, Administration Building  
Rural Route  
Salisaw  
Sequoyah County  
Oklahoma

HABS No. OK-31

Documentation: 3 exterior photos (1979)  
2 interior photos (1979)  
10 data pages (1975)

Walter Smalling, Jr., Photographer October 1979

OK-31-1 GENERAL VIEW OF BUILDING, FROM NORTHEAST

OK-31-2 WEST (REAR) ELEVATION

OK-31-3 EAST (FRONT) AND SOUTH ELEVATIONS

OK-31-4 AUDITORIUM, THIRD FLOOR, LOOKING WEST

OK-31-5 AUDITORIUM, THIRD FLOOR, LOOKING EAST